



Array Networks Announcement: System Reboot Caused by HTTP Upgrade Field (ID-117373)

Revision History

Revision	Date	Description
V1.0	February 23, 2023	Initial Publication.

Issue Description

In the SLB scenario of HTTP and HTTPS services, if the HTTP header is too long and contains the HTTP Upgrade header field, system reboot may be triggered.

Impact

The issue may affect the following versions:

ArrayOS APV 8.6.1.189 - ArrayOS APV 8.6.1.232

ArrayOS APV 10.4.0.2 - ArrayOS APV 10.4.0.39

Solution & Guidelines

This issue has been resolved in the following versions:

ArrayOS APV 8.6.1.239 and later versions

ArrayOS APV 10.4.0.43 and later versions

ArrayOS APV 10.4.2.3 and later versions

ArrayOS APV 10.4.3.1 and later versions